



MUD PUMP CLUTCH DRIVE ASSEMBLY

\$6,500.00





PRODUCT DESCRIPTION

Part # 142197QD; Revision B

ADDITIONAL INFORMATION

Color	Red
Condition	Good
Location	Moab Utah
Manufacturer	Eaton
Year	1995
Model	Airflex 10GB300