





LANARK DRAWWORKS

\$17,500.00









PRODUCT DESCRIPTION

Mostly Rebuilt

New Clutches
Removed from a Lanark 2500 Drill Rig

5/8" or 3/4" Cable
Double 4" Wide X 22" Brakes Per Drum
Drum Width: 18"

Two Plate 14" Wichita Air Clutches (Replaced, New)

2-1/2" Drive Shaft Coming Out of Right Angle Drive

Right Angle Drive: Feels perfect -- not too tight and not too loose. Backlash feels right.

** Left handed turn / Turns counter clock wise

Click here for detailed dimensions

ADDITIONAL INFORMATION

Color Location Manufacturer Black, Grey Moab Utah Lanark