



# LANARK DRAWWORKS

**\$17,500.00**

---





## PRODUCT DESCRIPTION

Mostly Rebuilt  
New Clutches

Removed from a Lanark 2500 Drill Rig

5/8" or 3/4" Cable

Double 4" Wide X 22" Brakes Per Drum

Drum Width: 18"

Two Plate 14" Wichita Air Clutches (Replaced, New)

2-1/2" Drive Shaft Coming Out of Right Angle Drive

Right Angle Drive: Feels perfect -- not too tight and not too loose. Backlash feels right.

[Click here for detailed dimensions](#)

## ADDITIONAL INFORMATION

<b>Color</b>	Black, Grey
<b>Location</b>	Moab Utah
<b>Manufacturer</b>	Lanark