



LANARK DRAWWORKS

\$17,500.00





PRODUCT DESCRIPTION

Mostly Rebuilt
New Clutches
Removed from a Lanark 2500 Drill Rig
5/8" or 3/4" Cable
Double 4" Wide X 22" Brakes Per Drum
Drum Width: 18"
Two Plate 14" Wichita Air Clutches (Replaced, New)
2-1/2" Drive Shaft Coming Out of Right Angle Drive
Right Angle Drive: Feels perfect -- not too tight and not too loose. Backlash
feels right.

[Click here for detailed dimensions](#)

ADDITIONAL INFORMATION

Color	Black, Grey
Location	Moab Utah
Manufacturer	Lanark