





## SPEEDSTAR 18" ROTARY TABLE

\$37,500.00











## **PRODUCT DESCRIPTION**

18" Speedstar Rotary Table
like new
Ring & Pinion
changed oil 2/2024
NO MASTER BUSHING

Page: 2